



basic education

Department:
Basic Education
REPUBLIC OF SOUTH AFRICA

**NATIONAL
SENIOR CERTIFICATE**

GRADE 12

MECHANICAL TECHNOLOGY

NOVEMBER 2015

MEMORANDUM

MARKS: 200

This memorandum consists of 19 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS

- 1.1 B ✓ (1)
- 1.2 B ✓ (1)
- 1.3 B ✓ (1)
- 1.4 A ✓ (1)
- 1.5 C ✓ / D (1)
- 1.6 B ✓ (1)
- 1.7 A ✓ (1)
- 1.8 D ✓ (1)
- 1.9 A ✓ (1)
- 1.10 D ✓ (1)
- 1.11 D ✓ (1)
- 1.12 C ✓ (1)
- 1.13 B ✓ (1)
- 1.14 B ✓ (1)
- 1.15 A ✓ (1)
- 1.16 B ✓ (1)
- 1.17 A ✓ (1)
- 1.18 D ✓ (1)
- 1.19 A ✓ B for Afrikaans only (1)
- 1.20 C ✓ (1)

[20]

QUESTION 2: SAFETY**2.1 Personal Safety Angle grinder**

- Wear eye safety protection✓
- Wear ear plugs or muffs✓
- Wear safety boots with steel toe caps✓
- Wear overalls ✓Leather apron
- Wear gloves✓

(Any 3 x 1)

(3)

2.2 Safety – Hydraulic Press

- The predetermined pressure of the hydraulic press must not be exceeded✓
- Ensure the pressure gauges is in a working order ✓
- Platform on which the work piece rests must be rigid and square with the cylinder of the press ✓
- The prescribed equipment must be used✓
- Check that securing pins for the platform are fitted properly✓
- Check on hydraulic pipes for leaks/ oil on floor✓
- Bearing need to be placed in a suitable jig✓

(Any 3 x 1)

(3)

2.3 Safety – Spring tester

- Be very careful that the jaws/clamp of the spring tester does not slip out✓
- Use correct attachments of the valve spring tester to compress the spring. ✓
- Do not stretch or compress the spring more than indicated in the specification ✓

(Any 2 x 1)

(2)

2.4 Safety – Bearing and Gear puller

- Make sure that the puller is the right one to use ✓
- Do not use a hammer on the puller ✓
- Use the correct spanner to tighten the clamps and to pull off the object ✓
- Make certain that the puller is at a 90° to the work piece ✓
- Legs of the puller must not be worn
- Use the slip cover to prevent injury
- When working with the puller do not work directly behind the puller in case it slips

(Any 2 x 1)

(2)

[10]

QUESTION 3: TOOLS AND EQUIPMENT**3.1 Tests**

- 3.1.1 A **cylinder leakage tester** is used to check whether gases leak ✓
from the cylinder in the engine during compression stroke. ✓ (2)
- 3.1.2 The purpose of the **fuel pressure tester** is to test the fuel
operating pressure in the system ✓ and fuel pressure in the fuel
line that runs to the direct injection. ✓ (2)
- 3.1.3 The purpose of the **torsion tester** is to investigate the relationship
between momentum or torque applied to material and influence of
material length and torsional deflection. ✓✓ (2)

3.2 Reasons to perform cylinder leakage test

- Power loss
 - Low compression
 - To determine whether cylinder head gasket has blown ✓
 - Oil consumption due to excessive leakage past the piston rings ✓
 - To identify leaking valves as a cause of excessive smoking ✓
- (Any 2 x 1) (2)

3.3 Reasons for high CO reading


- Rich mixture setting ✓
 - Incorrect idle speed ✓
 - Clogged air filter ✓
 - Faulty choke ✓
 - Faulty injectors ✓
- (Any 2 x 1) (2)

3.4 Tests that can be performed using a multi-meter

- Current flow ✓
 - Voltage test ✓ Battery
 - Resistance test ✓
 - Transistor test ✓
 - Continuity test ✓
 - Temperature ✓
 - Diode and capacitor testing ✓
- (Any 2 x 1) (2)

[12]

4.1 Iron-carbon equilibrium diagram



(9)

4.2 Iron-carbon Structures

4.2.1 **Pearlite** is the combination of ferrite and cementite ✓ and it contains 0,83% of carbon content before heat treatment ✓

(2)

4.2.2 **Cementite** is formed when carbon content rises above 0,83%, ✓ the carbon combines with pearlite crystals to form a very hard structure. ✓

(2)

[13]

QUESTION 5: TERMINOLOGY**5.1 Calculation – spur gear**

$$\begin{aligned}
 5.1.1 \quad \text{Module} &= \frac{\text{PCD}}{T} \\
 &= \frac{108}{36} \quad \checkmark \\
 &= 3 \quad \checkmark
 \end{aligned}$$

(2)

$$\begin{aligned}
 5.1.2 \quad \text{OD} &= \text{PCD} + 2m \\
 &= 108 + 2(3) \quad \checkmark \\
 &= 108 + 6 \quad \checkmark \\
 &= 114 \text{ mm} \quad \checkmark
 \end{aligned}$$

(3)

$$\begin{aligned}
 5.1.3 \quad \text{Cutting depth} &= 2,157 \text{ m} & \text{or} & & 2,25 \text{ m} \\
 &= 2,157 \times 3 \quad \checkmark & & & 2,25 \times 3 \quad \checkmark \\
 &= 6,47 \text{ mm} \quad \checkmark & & & 6,75 \text{ mm} \quad \checkmark
 \end{aligned}$$

(2)

$$\begin{aligned}
 5.1.4 \quad \text{Addendum} &= m \\
 &= 3 \text{ mm} \quad \checkmark
 \end{aligned}$$

(1)

$$\begin{aligned}
 5.1.5 \quad \text{Dedendum} &= 1,157 \text{ m} & \text{or} & & 1,25 \text{ m} \\
 &= 1,157 \times 3 \quad \checkmark & & & 1,25 \times 3 \quad \checkmark \\
 &= 3,47 \text{ mm} \quad \checkmark & & & 3,75 \text{ mm} \quad \checkmark
 \end{aligned}$$

(2)

$$\begin{aligned}
 5.1.6 \quad \text{Circular pitch} &= m \times \pi \\
 &= 3 \times \pi \quad \checkmark \\
 &= 9,43 \text{ mm} \quad \checkmark & \text{or} & & 9,42 \text{ mm} \quad \checkmark
 \end{aligned}$$

(2)

$$\begin{aligned}
 5.1.7 \quad \text{Clearance} &= 0,157 \text{ m} & \text{or} & & 0,25 \text{ m} \\
 &= 0,157 \times 3 \quad \checkmark & & & 0,25 \times 3 \quad \checkmark \\
 &= 0,47 \text{ mm} \quad \checkmark & & & 0,75 \text{ mm} \quad \checkmark
 \end{aligned}$$

(2)

5.2 Advantages for compound slide:

- The chips have a better chance of curling away, which prevents tearing of the thread. This results in a better finish. ✓
- The left edge of the cutting tool performs most of the work whilst the right edge helps to polish the thread. ✓
- The load on the tip of the cutting tool is less than the cross-slide method. ✓
- If the cutting tool has broken down, it is easy to pick up the thread ✓
- Faster than the cross slide method ✓
- Can cut a larger screw pitch ✓

(Any 2 x 1) (2)

5.3 Disadvantages screw cutting – cross-slide method:

- The point of the tool, which is the weakest part of the tool, does most of the cutting. ✓
- Because both edges of the tool do the cutting, two chips curl onto each other. This can result in a torn thread. ✓
- A large load can damage the cutting tool/cutting edge. ✓
- Slower method ✓

(Any 2 x 1) (2)

5.4 Indexing:

$$\begin{aligned} \text{Indexing} &= \frac{40}{n} \\ &= \frac{40}{72} && \checkmark \\ &= \frac{10}{18} \times \frac{3}{3} \quad \text{OR} \quad \frac{5}{9} \times \frac{6}{6} && \checkmark \\ &= \frac{30}{54} && \checkmark \end{aligned}$$

No full turns and 30 holes in a 54 -hole plate ✓

(4)

5.5 Advantages of Up-cut milling

- A quick feed may be used ✓
- Vibration experienced is less ✓
- Less strain on the cutter and arbor ✓
- There is a positive pressure on the feed screw spindle and nuts because the direction of the cutter is against the direction of the feed ✓
- Metals with hard scale, start the cut under the scale where the metal is softer, this extends the life of the cutter ✓
- More accurate (precise) ✓
- Better finish ✓

(Any 2 x 1) (2)

5.6 Disadvantages of Down-cut milling

- A fine feed must be used ✓
- Vibration of the arbor is unavoidable ✓
- The cutter will come into contact with the hard scale of a scale material, which is harmful to the cutter teeth
- Cutter get blunt more easily ✓
- Poor finish ✓
- Slack on the table-feed must be eliminated ✓

(Any 2 x 1) (2)

5.7 Calculate: parallel key

5.7.1

$$\begin{aligned} \text{Width} &= \frac{D}{4} && \checkmark \\ &= \frac{42}{4} && \checkmark \\ &= 10,5 \text{ mm} && \end{aligned}$$

(2)

5.7.2

$$\begin{aligned} \text{Thickness} &= \frac{D}{6} && \checkmark \\ &= \frac{42}{6} && \checkmark \\ &= 7 \text{ mm} && \end{aligned}$$

(2)
[30]

QUESTION 6: JOINING METHODS**6.1 Shielding gas**

It forms the arc plasma, stabilises the arc on the metal being welded, and shields the arc and molten weld pool.

- Reduces atmospheric contamination✓✓
- It reduces excessive spatter and sparks✓✓

any 1 x 2 (2)

6.2 Relationship between voltage and wire feed

Higher voltage✓ results in a higher melt rate✓ therefore you need a higher feed rate.✓

(3)

6.3 Weld defects (causes)**6.3.1 Slag inclusion**

- Included angle too narrow✓
- Rapid chilling✓
- Welding temperature too low / current too low✓
- High viscosity of molten metal✓
- Slag not removed from previous weld run✓
- **Current setting to low**✓
- **Correct welding technique**✓
- **Surface contamination**✓

(Any 2 x 1) (2)

6.3.2 Incomplete penetration

- Speed too fast ✓
- Joint design faulty✓
- Electrode too large✓
- Current too low✓
- **Wrong welding technique**✓

(Any 2 x 1) (2)

6.4 Weld defects (preventative)**6.4.1 Porosity**

- Use correct current✓
- Hold a longer arc✓
- Use correct electrodes✓
- Check for impurities✓
- Must shield the weld✓
- Correct welding technique✓

(Any 2 x 1) (2)

6.4.2 Lack of fusion

- Use correct welding technique✓
- Use the correct size of electrode✓
- Use the correct current setting✓
- Prepare the plate bevel/V-groove accordingly✓
- Correct welding technique✓

(Any 2 x 1) (2)

6.5 Destructive tests**6.5.1 Free bend test**

- Measures the ductility of the weld deposit and the heat-affected area adjacent to the weld. ✓
- To determine the percentage of elongation of the weld. ✓ (2)

6.5.2 Nick break test

- It determines the internal quality of the weld ✓ and can reveal an internal defect if present. ✓ (2)

6.5.3 Machinability test

- It is used to determine the weld's hardness ✓ and its strength. ✓
- To determine the machinability of the weld ✓✓ (2)

6.6 Atmospheric contamination (MIGS/MAGS welding)

- Inadequate shielding gas-flow ✓
- Excessive shielding gas flow (this can cause aspiration of air into the gas stream) ✓
- A severely blocked gas nozzle or a damaged gas supply system (leaking hoses, fittings etc.) ✓
- Excessive wind in the welding area (this can blow away the gas shield) ✓ (4)

6.7 Transceiver


A unit that is used to send a sound wave (transmit) ✓ and then act as a receiver to listen to the ultrasonic wave as it reflected through the metal. ✓

- To determine defects ✓✓

(2)
[25]

QUESTION 7: FORCES

7.1 Equilibrant



7.1.1 $\sum HC = 280\cos 50^\circ - 200\cos 35^\circ - 300\cos 30^\circ - 350$
 $= 179,98 - 163,83 - 259,81 - 350$
 $= -593,66 \text{ N}$

✓✓✓✓
✓

(5)

7.1.2 $\sum VC = 280\sin 50^\circ + 300\sin 30^\circ - 200\sin 35^\circ$
 $= 214,49 + 150,0 - 114,72$
 $= 249,77 \text{ N}$

✓✓✓
✓


(4)

OR

7.1.1 Horizontal components	Magnitudes	7.1.2 Vertical components	Magnitudes
$300N\cos 30^\circ$	-259,81 N ✓	$280N\sin 50^\circ$	214,49N ✓
$200N\cos 35^\circ$	-163,83 N ✓	$300N\sin 30^\circ$	150,0 N ✓
350 N	-350 N ✓	0 N	0 N
$280N\cos 50^\circ$	179,98 N ✓	$200\sin 35^\circ$	-114,72N ✓
TOTAL	-593,66 N ✓	TOTAL	249,77 N ✓

7.1.3 $E^2 = HC^2 + VC^2$ ✓
 $E = \sqrt{-593,66^2 + 249,77^2}$ ✓
 $E = 644,06\text{N}$ ✓

7.1.4 $\text{Tan}\theta = \frac{VC}{HC}$ ✓
 $= \frac{249,77}{593,66}$ ✓
 $\theta = 22,82^0$ ✓
 $E = 644,06\text{N}$ at $22,82^0$ south of east ✓



(3)

OR

$= 22^0 49$ minutes south of east (3)

7.2 **Stress and Strain**

Stress = Pa
Diameter = m
Force = N

Force

$\text{Stress} = \frac{\text{force}}{\text{area}}$
 $\text{Force} = \text{Stress} \times \text{Area}$ ✓

$\text{Force} = 3500000 \times \frac{\pi \times 0,025^2}{4}$ ✓

$\text{Force} = 3,5 \times 10^6 \times 4,90873852 \times 10^{-4}$ ✓
 $= 1718,06 \text{ N}$

$\text{Force} = 1,72 \text{ kN}$ ✓ (4)

7.3 **Stress and Strain**

- A = Limit of proportionality ✓
- B = Elastic limit ✓
- C = Yield point ✓
- D = Maximum stress ✓
- E = Break stress / Break point ✓ (5)

7.4 Reactions

Taking moments around A

$$\begin{aligned} \overset{\curvearrowright}{=} & \overset{\curvearrowleft}{=} \\ (255 \times 1,125) + (800 \times 3,25) &= (B \times 7,75) + (350 \times 1) \checkmark \\ 286,88 + 2600 &= 7,75B + 350 \\ B &= 2536,88/7,75 \checkmark \\ B &= 327,34 \text{ N} \checkmark \end{aligned}$$

Taking moments around B

$$\begin{aligned} \overset{\curvearrowright}{=} & \overset{\curvearrowleft}{=} \\ A \times 7,75 &= (800 \times 4,5) + (255 \times 6,625) + (350 \times 8,75) \checkmark \\ A \times 7,75 &= 3600 + 1689,38 + 3062,5 \\ A &= 8351,88/7,75 \checkmark \\ A &= 1077,66 \text{ N} \checkmark \end{aligned}$$

(6)
[30]

QUESTION 8: MAINTENANCE

- 8.1 **Viscosity**
To ensure that the gears are well coated with oil and do not lose the barrier of lubrication between them. ✓ ✓ (2)
- 8.2 **Reason using SAE20W50**
This to ensure that the oil is able to satisfy the operational requirements over a range of temperature from start-up to running hot. ✓ ✓ (2)
- 8.3 **Pour point**
Pour point is the lowest temperature at which a liquid remains pourable. ✓ (1)
- 8.4 **Maintain cutting fluid**
- Avoid contamination of the cutting fluid by draining and regularly replacing it. ✓
 - Always clean the machine's splash tray of metal cutting after use. ✓
 - Regularly wipe cutting fluid splashes of machine parts. ✓
 - Ensure that the sump is topped up from time to time and check that there is sufficient flow of cutting fluid to the cutting tool. ✓
 - Filter oil on a regular basis ✓
 - Ensure that the correct soluble oil to water ratio is correct ✓
- (Any 3 x 1) (3)
- 8.5 **Belt drive maintenance**
Belt tends to stretch with prolonged use therefore they will need to be tightened periodically and checked for correct alignment.
To transmit maximum torque without slippage ✓ ✓ (2)
- 8.6 **Reason skimming flywheel**
The clutch plate presses against the flywheel. ✓ Due to friction between the clutch and flywheel it creates grooves/cracks in the flywheel. ✓ The grooves will need to be removed by a precision machining process known as skimming before the new clutch plate is fitted.
To ensure that the co-efficient of friction the surfaces are at its maximum. ✓
To reduce wear and protect the new clutch plate. ✓ (3)
- 8.7 **Grease**
- Grease has a very high viscosity to ensure that it coats ✓ and sticks ✓ to the bearing surface it is lubricating.
 - To reduce rust ✓
 - To reduce noise ✓
 - Helps cool the bearings ✓
 - Increases the lifespan of the bearings ✓
 - Reduces friction ✓

(2)
[15]

QUESTION 9: SYSTEMS AND CONTROL**9.1 Gear drives****9.1.1 Number of teeth idler**

$$\begin{aligned}
 N_A \times T_A &= N_B \times T_B \\
 T_B &= \frac{N_A \times T_A}{N_B} && \checkmark \\
 &= \frac{500 \times 46}{1000} && \checkmark \\
 &= 23 \text{ teeth} && \checkmark
 \end{aligned}$$

(3)

9.1.2 Rotation frequency of the output shaft

$$\begin{aligned}
 N_B \times T_B &= N_C \times T_C && N_A \times T_A = N_C \times T_C \\
 N_C &= \frac{N_B \times T_B}{T_C} && \checkmark && N_C = \frac{N_A \times T_A}{T_C} && \checkmark \\
 &= \frac{1000 \times 23}{60} && \checkmark && && = \frac{500 \times 46}{60} && \checkmark \\
 &= 383,33 \text{ r/min} && \checkmark && \text{OR} && = 383,33 \text{ r/min} && \checkmark
 \end{aligned}$$

(3)

9.2 Pulley Drives**9.2.1 Diameter of the driven pulley**

$$\begin{aligned}
 N_1 \times D_1 &= N_2 \times D_2 \\
 D_2 &= \frac{N_1 \times D_1}{N_2} && \checkmark \\
 &= \frac{7,2 \times 600}{12} && \checkmark \\
 &= 360 \text{ mm} && \checkmark
 \end{aligned}$$

(3)

9.2.2 Power transmitted:

$$\begin{aligned}
 P &= (T_1 - T_2) \pi D n \\
 P &= (300 - 120) \pi \times 0,6 \times 7,2 && \checkmark \\
 &= 2\,442,9 \text{ Watts} && \checkmark \\
 &= 2,44 \text{ kW} && \checkmark
 \end{aligned}$$

$$\begin{aligned}
 \frac{T_1}{T_2} &= 2,5 \\
 T_2 &= \frac{300}{2,5} && \checkmark \\
 &= 120 \text{ N}
 \end{aligned}$$

OR

$$P = (T_1 - T_2) \pi d n$$

$$P = (300 - 120) \pi \times 0,36 \times 12$$

$$= 2\,442,9 \text{ Watts}$$

$$= 2,44 \text{ kW}$$

✓

✓

$$\frac{T_1}{T_2} = 2,5$$

$$T_2 = \frac{300}{2,5}$$

$$= 120 \text{ N}$$

✓

(3)

9.3 Hydraulics

9.3.1 Fluid pressure

$$A_B = \frac{F^2}{4}$$

$$= \frac{F \times 0,076^2}{4}$$

$$= 4,536459792 \times 10^{-3} \text{ m}^2$$

✓

✓

$$P_B = \frac{F}{A_B}$$

$$= \frac{4000}{4,536459792 \times 10^{-3}} \text{ Pa}$$

$$= 881744,837 \text{ Pa}$$

$$= 881,74 \text{ kPa}$$

✓

✓

(4)

9.3.2 Diameter of piston A

$$P_A = P_B$$

$$P_B = \frac{F_A}{A_A}$$

$$A_A = \frac{F_A}{P_B}$$

$$A_A = \frac{140 \text{ N}}{881744,837 \text{ N/m}^2} \quad \checkmark$$

$$A_A = 1,5877609 \times 10^{-4}$$

$$A_A = 1,59 \times 10^{-4} \quad \checkmark$$

$$= \frac{\pi D^2}{4} \quad \checkmark$$

$$D = \sqrt{\frac{A_A \times 4}{\pi}} \quad \checkmark$$

$$= \sqrt{\frac{1,59 \times 10^{-4} \times 4}{\pi}} \quad \checkmark$$

$$= 0,0142182 \text{ m} \quad \checkmark$$

$$= 14,22 \text{ mm} \quad \checkmark$$

(5)

9.4 Traction Control

- Prevent wheel from spinning ✓ if the torque transmitted to any other wheel which exceeds the minimum traction ✓
- Safety feature ✓✓

(2)

9.5 Air Bags

It is seen as a passive safety feature because the driver and passengers in the vehicle do not need to activate the air bags ✓ or do anything to be protected by air bags. ✓

(2)

[25]

QUESTION 10: TURBINES**10.1 Reaction Turbine**

- Francis ✓
- Kaplan ✓
- Tyson ✓
- Gorlov ✓

(Any 2 x 1)

(2)

10.2 Impulse Turbine

- Impulse turbine changes the velocity of a water jet. ✓
- The jet pushes on the turbine's curved blades which changes the direction of the flow ✓
- The resulting change in momentum (impulse) causes a force on the turbine blades. ✓
- Since the turbine is spinning the force acts through a distance and the diverted water flow is left with diminished energy. ✓
- Prior to hitting the turbine blades the water's pressure is converted to kinetic energy by a nozzle and focused on the turbine. ✓
- No pressure change occurs at the turbine blades. ✓

(6)

10.3 Control of speed of steam turbine

To prevent the turbine rotor leading to an over-speed trip. This causes the nozzle valves that control the flow of steam to the turbine to close. ✓✓

(2)

10.4 Advantages of gas turbine

- Smooth running due to absence of reciprocating parts. ✓
- No rubbing parts such as piston so that internal friction and wear are almost eliminated. ✓
- Easy starting. ✓
- Can use wide range of fuels. ✓
- No water cooling system required. ✓
- Non-poisonous exhaust giving very little trouble with pollution ✓
- Require little routine maintenance. ✓
- Very high power-to-weight ratio, compared to reciprocating engines. ✓
- Moves in one direction only, with far less vibration than a reciprocating engine. ✓
- Low operating pressures. ✓
- High operation speeds ✓.
- Low lubricating oil cost and consumption. ✓

(Any 3 x 1)

(3)

10.5	Auxiliary power units <ul style="list-style-type: none">• To supply auxiliary power for larger machines. ✓• To supply compressed air for aircraft ventilation. ✓• Start power for larger jet engines, electrical and hydraulic power units. ✓	(Any 2 x 1)	(2)
10.6	Purpose of supercharger <ul style="list-style-type: none">• To fill the cylinder with an increased pressure that is higher than atmospheric pressure. ✓• To increase the compression pressure in the cylinder. ✓• To increase the volumetric efficiency of the engine.• To produce more engine power• Eliminates power loss above sea level ✓	(Any 2 x 1)	(2)
10.7	High altitude <p>At high altitude less oxygen is available for combustion. Loss of power ✓✓</p>		(2)
10.8	Advantage turbocharger <p>Uses the exhaust gases to operate the turbo charger. No loss of power - needed to drive supercharger ✓</p>		(1)
		TOTAL:	200

[20]